

Annual Drinking Water Quality Report

WEST SHORE PARK SUBDIVISION

IL0977370

Annual Water Quality Report for the period of January 1 to December 31, 2024

This report is intended to provide you with important information about your drinking water and the efforts made by the water system to provide safe drinking water.

The source of drinking water used by WEST SHORE PARK SUBDIVISION is Ground Water

For more information regarding this report contact:

Name Chad Karol_____

Phone 847-757-5507 / chadkarol@gmail.com _____

Este informe contiene información muy importante sobre el agua que usted bebe. Tradúzcalo ó hable con alguien que lo entienda bien.

Source of Drinking Water
The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.
Contaminants that may be present in source water include: - Microbial contaminants, such as viruses and bacteria, which may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife. - Inorganic contaminants, such as salts and metals, which can be naturally-occurring or result from urban storm water runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming. - Pesticides and herbicides, which may come from a variety of sources such as agriculture, urban storm water runoff, and residential uses. - Organic chemical contaminants, including synthetic and volatile organic chemicals, which are by-products of industrial processes and petroleum production, and can also come from gas stations, urban storm water runoff, and septic systems. - Radioactive contaminants, which can be naturally-occurring or be the result of oil and gas production and mining activities.

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the EPAs Safe Drinking Water Hotline at (800) 426-4791.
In order to ensure that tap water is safe to drink, EPA prescribes regulations which limit the amount of certain contaminants in water provided by public water systems. FDA regulations establish limits for contaminants in bottled water which must provide the same protection for public health.
Some people may be more vulnerable to contaminants in drinking water than the general population.
Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. EPA/CDC guidelines on appropriate means to lessen the risk of infection by Cryptosporidium and other microbial contaminants are available from the Safe Drinking Water Hotline (800-426-4791).
Lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. The drinking water supplier is responsible for providing high quality drinking water and removing lead pipes, but cannot control the variety of materials used in plumbing components in your home. You share the responsibility for protecting yourself and your family from the lead in your home plumbing. You can take responsibility by identifying and removing lead materials within your home plumbing and taking steps to reduce your family's risk.

Before drinking tap water, flush your pipes for several minutes by running your tap, taking a shower, doing laundry or a load of dishes. You can also use a filter certified by an American National Standard Institute accredited certifier to reduce lead in drinking water. If you are concerned about lead in your water, you may wish to have your water tested, contact _____ at _____. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available at <http://www.epa.gov/safewater/lead>.

Source Water Information

Source Water Name	Type of Water	Report Status	Location
WELL 1 (20249)	GW	__ACTIVE__	AT GSR ON WEST SHORE DR
WELL 2 (01055)	GW	__ACTIVE__	__42.25275, -88.01347__
WELL 3 (01550)	GW	__ACTIVE__	__42.25296, -88.01355__

Source Water Assessment

We want our valued customers to be informed about their water quality. If you would like to learn more, please feel welcome to attend any of our regularly scheduled meetings. The source water assessment for our supply has been completed by the Illinois EPA. If you would like a copy of this information, please stop by City Hall or call our water operator at ____jdesbiens@gha-engineers.com____. To view a summary version of the completed Source Water Assessments, including: Importance of Source Water; Susceptibility to Contamination Determination; and documentation/recommendation of Source Water Protection Efforts, you may access the Illinois EPA website at <http://www.epa.state.il.us/cgi-bin/wp/swap-fact-sheets.pl>.

Source of Water: WEST SHORE PARK SUBDIVISIONBased on information obtained in a Well Site Survey, published in 1990 by the Illinois EPA, no potential sources or possible problem sites were identified within the survey area of West Shore Park Subdivision wells. However, information provided by the Leaking Underground Storage Tank and Remedial Project Management Sections of the Illinois EPA indicated several additional sites with ongoing remediation which may be of concern.The Illinois EPA has determined that the West Shore Park Subdivision Community Water Supply's source water is not susceptible to contamination. This determination is based on a number of criteria including: monitoring conducted at the wells; monitoring conducted at the entry point to the distribution system; and the available hydrogeologic data on the wells.Furthermore, in anticipation of the U.S. EPA's proposed Ground Water Rule, the Illinois EPA has determined that the West Shore Park Subdivision Community Water Supply is not vulnerable to viral contamination. This determination is based upon the evaluation of the following criteria during the Vulnerability Waiver Process: the subdivision's wells are properly constructed with sound integrity and proper site conditions; a hydrogeologic barrier exists which should prevent pathogen movement; all potential routes and sanitary defects have been mitigated such that the source water is adequately protected; monitoring data did not indicate a history of disease outbreak; and the sanitary survey of the water supply did not indicate a viral contamination threat. Because the subdivision's wells are constructed in a confined aquifer, which should prevent the movement of pathogens into the wells, well hydraulics were not considered to be a significant factor in this vulnerability determination. Hence, well hydraulics were not evaluated for this groundwater supply.

Lead and Copper

Definitions:

Action Level: The concentration of a contaminant which, if exceeded, triggers treatment or other requirements which a water system must follow.

Action Level Goal (ALG): The level of a contaminant in drinking water below which there is no known or expected risk to health. ALGs allow for a margin of safety.

Copper Range: _____0_____ to _____150_____

Lead Range: _____0_____ to _____40_____

To obtain a copy of the system's lead tap sampling data: ____chadkarol@gmail.com_____

CIRCLE ONE: Our Community Water Supply **has**/~~has not~~ developed a service line material inventory.

To obtain a copy of the system's service line inventory: ____chadkarol@gmail.com_____

Lead and Copper	Date Sampled	MCLG	Action Level (AL)	90th Percentile	# Sites Over AL	Units	Violation	Likely Source of Contamination
Copper	2024	1.3	1.3	0.15	0	ppm	N	Corrosion of household plumbing systems; Erosion of natural deposits.
Lead	2024	0	15	9.62	1	ppb	N	Corrosion of household plumbing systems; Erosion of natural deposits.

Water Quality Test Results

Definitions:	The following tables contain scientific terms and measures, some of which may require explanation.
Avg:	Regulatory compliance with some MCLs are based on running annual average of monthly samples.
Level 1 Assessment:	A Level 1 assessment is a study of the water system to identify potential problems and determine (if possible) why total coliform bacteria have been found in our water system.
Level 2 Assessment:	A Level 2 assessment is a very detailed study of the water system to identify potential problems and determine (if possible) why an E. coli MCL violation has occurred and/or why total coliform bacteria have been found in our water system on multiple occasions.
Maximum Contaminant Level or MCL:	The highest level of a contaminant that is allowed in drinking water. MCLs are set as close to the MCLGs as feasible using the best available treatment technology.

Water Quality Test Results

Maximum Contaminant Level Goal or MCLG:	The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.
Maximum residual disinfectant level or MRDL:	The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.
Maximum residual disinfectant level goal or MRDLG:	The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.
na:	not applicable.
mrem:	millirems per year (a measure of radiation absorbed by the body)
ppb:	micrograms per liter or parts per billion - or one ounce in 7,350,000 gallons of water.
ppm:	milligrams per liter or parts per million - or one ounce in 7,350 gallons of water.
Treatment Technique or TT:	A required process intended to reduce the level of a contaminant in drinking water.

Regulated Contaminants

Disinfectants and Disinfection By-Products	Collection Date	Highest Level Detected	Range of Levels Detected	MCLG	MCL	Units	Violation	Likely Source of Contamination
Chlorine	2024	0.9	0.32 - 1.96	MRDLG = 4	MRDL = 4	ppm	N	Water additive used to control microbes.
Haloacetic Acids (HAA5)	2024	10	10.3 - 10.3	No goal for the total	60	ppb	N	By-product of drinking water disinfection.
Total Trihalomethanes (THM)	2024	35	35.1 - 35.1	No goal for the total	80	ppb	N	By-product of drinking water disinfection.
Inorganic Contaminants	Collection Date	Highest Level Detected	Range of Levels Detected	MCLG	MCL	Units	Violation	Likely Source of Contamination
Barium	2024	0.0199	0.0199 - 0.0199	2	2	ppm	N	Discharge of drilling wastes; Discharge from metal refineries; Erosion of natural deposits.
Fluoride	2024	0.98	0.98 - 0.98	4	4.0	ppm	N	Erosion of natural deposits; Water additive which promotes strong teeth; Discharge from fertilizer and aluminum factories.
Iron	2024	0.117	0.117 - 0.117		1.0	ppm	N	This contaminant is not currently regulated by the USEPA. However, the state regulates. Erosion of natural deposits.
Sodium	2024	65400	65400 - 65400			ppb	N	Erosion from naturally occuring deposits. Used in water softener regeneration.
Radioactive Contaminants	Collection Date	Highest Level Detected	Range of Levels Detected	MCLG	MCL	Units	Violation	Likely Source of Contamination
Gross alpha excluding radon and uranium	2024	5.84	5.84 - 5.84	0	15	pCi/L	N	Erosion of natural deposits.



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		West Shore Park Subdivision			System ID Number:		IL0977370		Current Inventory Date:		4/11/2025			
*Please enter totals in the empty box next to each category	Total Service lines:	180	Total Lead:	3	Total Non-Lead:	155	Total Galvanized Requiring replacement:	0	Total Unknown:	22	Website link to Material Inventory:				

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, If customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Galvanized (G)							
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)							
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)							
		Cast/Ductile Iron or Transite (O)					Lead (L)										
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
		Unknown (U)					Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Leave blank if no Lead Service Line was replaced.							
		Unknown Not Lead (UNL)					Unknown (U)	Unknown (U)									
		Unknown Not Lead (UNL)					Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
19196 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1955	1955	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19197 W Forest Ln Mundelein IL 60060	N/A	N	Y	1959	1959	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19226 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1946	1946	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19231 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1940	1940	Survey Response	CLS	u	u	U	N	N/R	N			N	
19231 W Forest Ln Mundelein IL 60060	N/A	N	Y	1948	1948	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19239 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1957	1957	Survey Response	CLS	u	u	U	N	N/R	N			N	
19239 W Forest Ln Mundelein IL 60060	N/A	N	Y	2016	2016	Survey Response	C	c	c	NL	N	N/R	N			N	
19240 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1955	1955	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19245 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1938	1938	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19251 W Forest Ln Mundelein IL 60060	N/A	N	Y	2008	2008	Survey Response	C	c	c	NL	N	N/R	N			N	
19263 W Forest Ln Mundelein IL 60060	N/A	N	Y	1945	1945	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19264 W Fairview Dr Mundelein IL 60060	N/A	N	Y	2017	2017	Survey Response	C	c	c	NL	N	N/R	N			N	
19270 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1958	1958	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19271 W Forest Ln Mundelein IL 60060	N/A	N	Y	2005	2005	Survey Response	C	c	c	NL	N	N/R	N			N	
19275 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1938	1938	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19279 W Forest Ln Mundelein IL 60060	N/A	N	Y	1928	1928	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19289 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1964	1964	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19295 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1939	1939	Survey Response	CLS	l	l	L	N	4/11/2025	N			N	
19295 W Forest Ln Mundelein IL 60060	N/A	N	Y	2020	2020	Survey Response	C	c	c	NL	N	N/R	N			N	
19297 Forest Ln Mundelein IL 60060	N/A	N	Y	1936	1936	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19299 W Forest Ln Mundelein IL 60060	N/A	N	Y	1979	1979	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19303 W Forest Ln Mundelein IL 60060	N/A	N	Y	1942	1942	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19307 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1933	1933	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19311 W Forest Ln Mundelein IL 60060	N/A	N	Y	1942	1942	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19313 W Forest Ln Mundelein IL 60060	N/A	N	Y	1933	1933	Survey Response	CLS	g	g	NL	N	N/R	N			N	
19314 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1925	1925	Survey Response	CLS	u	u	U	N	N/R	N			N	
19317 W Forest Ln Mundelein IL 60060	LP3S012	N	n	1928	1928	Survey Response	CLS	u	u	U	N	N/R	N			N	

19319 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1936	1936	Survey Response	CLS	u	u	U	N	N/R	N			N	
19330 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1948	1948	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19335 W Forest Ln Mundelein IL 60060	N/A	N	Y	1987	1987	Survey Response	C	c	c	NL	N	N/R	N			N	
19337 W Fairview Dr Mundelein IL 60060	LP35013	N	n	1967	1967	Survey Response	CLS	u	u	U	N	N/R	N			N	
19341 W Forest Ln Mundelein IL 60060	N/A	N	Y	1930	1930	Survey Response	CLS	u	u	U	N	N/R	N			N	
19343 W Forest Ln Mundelein IL 60060	N/A	N	Y	1977	1977	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19344 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1943	1943	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19344 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1987	1987	Survey Response	C	c	c	NL	N	N/R	N			N	
19347 W Prospect Dr Mundelein IL 60060	N/A	N	Y	1977	1977	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19347 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1998	1998	Survey Response	C	c	c	NL	N	N/R	N			N	
19349 W Forest Ln Mundelein IL 60060	N/A	N	Y	2001	2001	Survey Response	C	c	c	NL	N	N/R	N			N	
19350 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1923	1923	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19351 W Fairview Dr Mundelein IL 60060	LP35009	N	n	1951	1951	Survey Response	CLS	u	u	U	N	N/R	N			N	
19351 W Forest Ln Mundelein IL 60060	N/A	N	Y	2003	2003	Survey Response	C	c	c	NL	N	N/R	N			N	
19351 W Prospect Dr Mundelein IL 60060	N/A	N	Y	1975	1975	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19353 W Forest Ln Mundelein IL 60060	N/A	N	Y	1977	1977	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19353 W West Shore Dr Mundelein IL 60060	LP1A003	N	n	1985	1985	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19355 W Forest Ln Mundelein IL 60060	N/A	N	Y	1988	1988	Survey Response	C	c	c	NL	N	N/R	N			N	
19355 W Prospect Dr Mundelein IL 60060	N/A	N	Y	1961	1961	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19357 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19358 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1998	1998	Survey Response	C	c	c	NL	N	N/R	N			N	
19360 W Prospect Dr Mundelein IL 60060	N/A	N	Y	1986	1986	Survey Response	C	c	c	NL	N	N/R	N			N	
19363 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1977	1977	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19364 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1927	1927	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19366 W Prospect Dr Mundelein IL 60060	N/A	N	Y	1986	1986	Survey Response	C	c	c	NL	N	N/R	N			N	
19368 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19371 W Prospect Dr Mundelein IL 60060	LP1A020	N	n	1986	1986	Survey Response	C	c	c	NL	N	N/R	N			N	
19376 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1977	1977	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19377 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19382 W Prospect Dr Mundelein IL 60060	LP35010	N	n	1966	1966	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19383 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1990	1990	Survey Response	C	c	c	NL	N	N/R	N			N	
19385 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1978	1978	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19392 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1950	1950	Survey Response	CLS	g	g	NL	N	N/R	N			N	
19392 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19393 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1926	1926	Survey Response	CLS	u	u	U	N	N/R	N			N	
19395 W Prospect Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19398 W Fairview Dr Mundelein IL 60060	N/A	N	Y	2017	2017	Survey Response	C	c	c	NL	N	N/R	N			N	
19398 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1975	1975	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19405 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19406 W Prospect Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19407 W Forest Ln Mundelein IL 60060	N/A	N	Y	1995	1995	Survey Response	C	c	c	NL	N	N/R	N			N	
19407 W Prospect Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19412 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1933	1933	Survey Response	CLS	u	u	U	N	N/R	N			N	
19415 W Forest Ln Mundelein IL 60060	N/A	N	Y	1994	1994	Survey Response	C	c	c	NL	N	N/R	N			N	
19419 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1978	1978	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19421 W Prospect Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19422 W Prospect Dr Mundelein IL 60060	N/A	N	Y	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19423 W Forest Ln Mundelein IL 60060	N/A	N	Y	1994	1994	Survey Response	C	c	c	NL	N	N/R	N			N	
19424 W Fairview Dr Mundelein IL 60060	N/A	N	Y	2021	2021	Survey Response	C	c	c	NL	N	N/R	N			N	
19429 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1955	1955	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19429 W Forest Ln Mundelein IL 60060	N/A	N	Y	1994	1994	Survey Response	C	c	c	NL	N	N/R	N			N	
19432 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1956	1956	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19433 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1955	1955	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19435 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1958	1958	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19437 W Forest Ln Mundelein IL 60060	N/A	N	Y	1994	1994	Survey Response	C	c	c	NL	N	N/R	N			N	
19441 W Prospect Dr Mundelein IL 60060	LP1A019	N	n	1986	1986	Survey Response	C	c	c	NL	N	N/R	N			N	
19445 W Forest Ln Mundelein IL 60060	N/A	N	Y	1994	1994	Survey Response	C	c	c	NL	N	N/R	N			N	
19449 W Forest Ln Mundelein IL 60060	N/A	N	Y	1993	1993	Survey Response	C	c	c	NL	N	N/R	N			N	
19454 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1936	1936	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19457 W Fairview Dr Mundelein IL 60060	N/A	N	Y	1972	1972	Survey Response	CLS	l	l	L	N	4/11/2025	N			N	

19481 W University Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	u	u	U	N	N/R	N			N	
19481 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1963	1963	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19485 W University Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19520 W University Dr Mundelein IL 60060	N/A	N	Y	1937	1937	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19521 W University Dr Mundelein IL 60060	N/A	N	Y	1997	1997	Survey Response	C	c	c	NL	N	N/R	N			N	
19527 W University Dr Mundelein IL 60060	LP35016	N	n	1974	1974	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19536 W University Dr Mundelein IL 60060	N/A	N	Y	1979	1979	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19539 W University Dr Mundelein IL 60060	LP35005	N	n	1977	1977	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19540 W University Dr Mundelein IL 60060	N/A	N	Y	1975	1975	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19541 W University Dr Mundelein IL 60060	N/A	N	Y	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19552 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1950	1950	Survey Response	CLS	g	g	NL	N	N/R	N			N	
19553 W West Shore Dr Mundelein IL 60060	N/A	N	Y	2006	2006	Survey Response	C	c	c	NL	N	N/R	N			N	
19561 W University Dr Mundelein IL 60060	N/A	N	Y	1975	1975	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19562 W University Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19565 W West Shore Dr Mundelein IL 60060	N/A	N	Y	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
19591 W West Shore Dr Mundelein IL 60060	LP35007	N	n	1975	1975	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26597 N Kenwood, Mundelein, IL 60060	N/A	N	Y	2005	2005	Survey Response	C	c	c	NL	N	N/R	N			N	
26601 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1918	1918	Survey Response	CLS	g	g	NL	N	N/R	N			N	
26611 N Kenwood Ct Mundelein, IL 60060	N/A	N	Y	1958	1958	Survey Response	CLS	u	u	U	N	N/R	N			N	
26617 N Oakdale Ln Mundelein IL 60060	LP35018	N	n	1938	1938	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26619 N Kenwood, Mundelein, IL 60060	N/A	N	Y	1930	1930	Survey Response	CLS	p	p	NL	N	N/R	N			N	
26630 N Circle Dr Mundelein IL 60060	N/A	N	Y	1851	1851	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26633 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	2008	2008	Survey Response	C	c	c	NL	N	N/R	N			N	
26635 N Circle Dr Mundelein IL 60060	N/A	N	Y	1944	1944	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26639 N Kenwood, Mundelein IL 60060	N/A	N	Y	1988	1988	Survey Response	C	c	c	NL	N	N/R	N			N	
26640 N Circle Dr Mundelein IL 60060	LP1A001	N	n	1985	1985	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26641 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	2008	2008	Survey Response	C	c	c	NL	N	N/R	N			N	
26649 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	2009	2009	Survey Response	C	c	c	NL	N	N/R	N			N	
26650 N Circle Dr Mundelein IL 60060	N/A	N	Y	1967	1967	Survey Response	CLS	u	u	U	N	N/R	N			N	
26665 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1993	1993	Survey Response	C	c	c	NL	N	N/R	N			N	
26670 N Circle Dr Mundelein IL 60060	N/A	N	Y	1962	1962	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26671 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1985	1985	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26680 N Circle Dr Mundelein IL 60060	LP35014	N	n	1953	1953	Survey Response	CLS	l	l	L	N	4/11/2025	N			N	
26681 N Circle Dr Mundelein IL 60060	N/A	N	Y	1952	1952	Survey Response	CLS	u	u	U	N	N/R	N			N	
26683 N Oakdale Ln Mundelein IL 60060	LP35006	N	n	1977	1977	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26689 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	2005	2005	Survey Response	C	c	c	NL	N	N/R	N			N	
26696 N Circle Dr Mundelein IL 60060	N/A	N	Y	1963	1963	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26697 N Circle Dr Mundelein IL 60060	N/A	N	Y	1932	1932	Survey Response	CLS	u	u	U	N	N/R	N			N	
26704 N Circle Dr Mundelein IL 60060	N/A	N	Y	1978	1978	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26705 N Circle Dr Mundelein IL 60060	N/A	N	Y	1941	1941	Survey Response	CLS	u	u	U	N	N/R	N			N	
26705 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1964	1964	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26713 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1974	1974	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26720 N Circle Dr Mundelein IL 60060	N/A	N	Y	1955	1955	Survey Response	CLS	u	u	U	N	N/R	N			N	
26721 N Circle Dr Mundelein IL 60060	N/A	N	Y	1943	1943	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26721 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1977	1977	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26729 N Circle Dr Mundelein IL 60060	N/A	N	Y	2007	2007	Survey Response	C	c	c	NL	N	N/R	N			N	
26729 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1994	1994	Survey Response	C	c	c	NL	N	N/R	N			N	
26735 N Circle Dr Mundelein IL 60060	N/A	N	Y	1926	1926	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26736 N Circle Dr Mundelein IL 60060	N/A	N	Y	1993	1993	Survey Response	C	c	c	NL	N	N/R	N			N	
26737 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	2008	2008	Survey Response	C	c	c	NL	N	N/R	N			N	
26741 N Circle Dr Mundelein IL 60060	N/A	N	Y	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26745 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1962	1962	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26747 N Circle Dr Mundelein IL 60060	N/A	N	Y	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26751 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1995	1995	Survey Response	C	c	c	NL	N	N/R	N			N	
26752 N Circle Dr Mundelein IL 60060	N/A	N	Y	1938	1938	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26757 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1958	1958	Survey Response	CLS	u	u	U	N	N/R	N			N	
26759 N Circle Dr Mundelein IL 60060	N/A	N	Y	1959	1959	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26760 N Circle Dr Mundelein IL 60060	N/A	N	Y	1975	1975	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26765 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1937	1937	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26767 N Circle Dr Mundelein IL 60060	N/A	N	Y	1959	1959	Survey Response	CLS	u	u	U	N	N/R	N			N	

26768 N Circle Dr Mundelein IL 60060	N/A	N	Y	2007	2007	Survey Response	C	c	c	NL	N	N/R	N			N	
26773 N Circle Dr Mundelein IL 60060	N/A	N	Y	1953	1953	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26773 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26779 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26781 N Circle Dr Mundelein IL 60060	N/A	N	Y	1986	1986	Survey Response	C	c	c	NL	N	N/R	N			N	
26784 N Circle Dr Mundelein IL 60060	N/A	N	Y	1972	1972	Survey Response	CLS	u	u	U	N	N/R	N			N	
26787 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1933	1933	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26793 N Circle Dr Mundelein IL 60060	N/A	N	Y	1933	1933	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26795 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1984	1984	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26803 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1937	1937	Survey Response	CLS	u	u	U	N	N/R	N			N	
26805 N Circle Dr Mundelein IL 60060	N/A	N	Y	1922	1922	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26811 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1961	1961	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26817 N Circle Dr Mundelein IL 60060	LP3S015	N	n	1962	1962	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26821 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1953	1953	Survey Response	CLS	u	u	U	N	N/R	N			N	
26829 N Circle Dr Mundelein IL 60060	N/A	N	Y	1987	1987	Survey Response	C	c	c	NL	N	N/R	N			N	
26831 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1933	1933	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26837 N Circle Dr Mundelein IL 60060	N/A	N	Y	1970	1970	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26839 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1987	1987	Survey Response	C	c	c	NL	N	N/R	N			N	
26845 N Circle Dr Mundelein IL 60060	N/A	N	Y	1997	1997	Survey Response	C	c	c	NL	N	N/R	N			N	
26847 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1975	1975	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26855 N Oakdale Ln Mundelein IL 60060	LP1A002	N	n	1987	1987	Survey Response	C	c	c	NL	N	N/R	N			N	
26856 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1961	1961	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26863 N Oakdale Ln Mundelein IL 60060	LP1A004	N	n	1985	1985	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26864 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1950	1950	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26878 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26879 N Oakdale Ln Mundelein IL 60060	LP3S011	N	n	1937	1937	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26880 N Circle Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26886 N Oakdale Ln Mundelein IL 60060	N/A	N	Y	1977	1977	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26893 N Circle Dr Mundelein IL 60060	LP3S017	N	n	1976	1976	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26896 N Circle Dr Mundelein IL 60060	LP3S008	N	n	1956	1956	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26904 N Circle Dr Mundelein IL 60060	N/A	N	Y	1973	1973	Survey Response	CLS	p	p	NL	N	N/R	N			N	
26910 N Circle Dr Mundelein IL 60060	N/A	N	Y	1962	1962	Survey Response	CLS	c	c	NL	N	N/R	N			N	
26957 N Highland Terr Mundelein IL 60060	N/A	N	Y	1945	1945	Survey Response	CLS	c	c	NL	N	N/R	N			N	